


1991



**CORROSION BELOW:
SEWER STRUCTURES**



During the late 1980's in Bar Harbor, NJ the municipality of Long Beach Island was forced to start replacing manholes after only a few years in the ground due to Hydrogen-Sulfide corrosion.

2006



2011



They also tried polyethylene manholes which lasted less than two years.

2017



In 1991 they decided to protect their manholes using our

**DURA-PLATE 100
CORROSION
RESISTANT LINER**

2019



and these manholes are still being protected to this day by the original Dura-Plate Liner, installed over 30 years ago.

2021



www.a-lok.com
info@a-lok.com
215-547-3366
800-822-2565